

ADVANCED MACHINING

BETP 3584


MULTI-AXIS PROFILE CONTOURING IN 4/5 AXIS MACHINING

Syahrul Azwan bin Sundi @ Suandi
syahrul.azwan@utem.edu.my

Multi-Axis Profile Contouring



- ☐ Multi-Axis Profile Contouring is actually an advancement from Profile Contouring Operation in 3-Axis Machining.
- ☐ Despite performing profile contouring process on the 3-Axis surfaces, Profile Contouring can also be utilized to machine on slanted or angled surfaces which also known as 4/5 Axis surfaces.
- ☐ Multi-Axis Profile Contouring ONLY appropriate for 5-Axis Indexing program NOT simultaneous motion.
- ☐ Ultimately, Multi-Axis Profile Contouring offering broaden flexibility in preparing CAM program for any given CAD model.

Multi-Axis Profile Contouring



- ✓ From the given CAD Model, there are **few areas** have been **identified appropriate to perform Multi-Axis Profile Contouring**.
- ✓ In **chapter 4**, **Angled or Chamfer profiles** are machined by using **Isoparametric Operation** in 3-Axis as well as 5-Axis way.
- ✓ However, this time **Multi-Axis Profile Contouring** shall be utilized to **machine approximately the same profiles** which definitely resulted faster in programming time and greater surface finish quality.

Multi-Axis Profile Contouring




Profile Contouring

- ✓ **Multi-Axis Profile Contouring** is actually using **Profile Contouring Definition** as the main operation
- ✓ Create and insert the desired Cutting Tool in the Resource List as well as in the Manufacturing Program
- ✓ Select the right **CUTTING TOOL– END MILL D10.0**

Multi-Axis Profile Contouring


2




- ✓ In TAB – 2, there are **Four (4) geometries** that need to be defined namely **Bottom Surface**, **Guiding Element** (Machining Guide), **Limit 1** and **Limit 2** (start and stop).
- ✓ **Bottom Surface** is **very important** because this surface will be the **reference surface for the Tool Axis**.
- ✓ In **Multi-Axis Profile Contouring** there is no **Tool Axis options**.
- ✓ **Tool Axis** will be **automatically change perpendicular** to the chosen **Bottom Surface**.

Multi-Axis Profile Contouring


1




Zig zag
One way
Helix



Zig Zag



One Way



Helix

✓ In **TAB – 1**, there are **Tool Path Style** or **Machining Strategy** can be determined namely Zig Zag, One Way and Helix.


✓ The best machining strategy is One Way. Better surface finish and longer tool life shall be gained if this strategy is chosen.

✓ On the other hand, **Machining Tolerance** representing how fine one path to another or one point to another point.

✓ The smaller the number is in Machining Tolerance will give better result in dimensional.

Multi-Axis Profile Contouring

1





Radial first
Axial first

Maximum depth of cut
Number of levels
Number of levels without top

- ✓ Still in **TAB – 1**, STEPOVER – There are Radial & Axial Strategy to be determined here.
- ✓ User can choose the **sequence** of tool path calculation either **Radial** or **Axial** first.
- ✓ On the other hand, there are **THREE (3)** options offered in **Axial Strategy** namely **Maximum Depth of Cut**, **Number of Levels** and **Number of Levels Without Top**.
- ✓ Options of **Maximum Depth of Cut** and **Number of Levels** can **ONLY** be used **IF Top Surface** is defined.

3


Multi-Axis Profile Contouring



- On the TAB-3, user **need to check cutting tool specification** is correct according to the machining process to be used.
- This is very important **to ensure the right machining simulation is calculated.**
- **No changes is allowed** to be done here.
- If there is **any modification needs to be made**, user need to go back to the **Resources List** and make necessary changes there.

4


Multi-Axis Profile Contouring




- There are **THREE (3)** types of **Feed Rates** which need to be defined namely **Approach, Machining & Retract**.
- **Color Coding** representing each Feed Rate are
 - **Approach = Yellow**
 - **Machining = Green**
 - **Retract = Blue**
- To view this, user needs to **change the setting** in **simulation TAB** into **Color Mode**.



- ❑ **Another Setting** that needs to be defined is **Spindle Speed** which **relying on the size, type & material** of the **cutting tool** as well as the **workpiece**.




Multi-Axis Profile Contouring




❑ Macro Setting for Approach consists of, Axial To Plane, Tool Axis, Axial To Plane and Motion to Point.

❑ Meanwhile, Macro Setting for Retract consists of Axial To Plane, Tool Axis and Axial To Plane.



Multi-Axis Profile Contouring



❑ Since **Multi-Axis Profile Contouring** is using for **4/5 Axis** position thus **Tool Axis** is very important to maintain the **cutting tool position 90 degree** before and after machining is done.

❑ **Tool Axis** is very useful to be used in **4/5 Axis** motion to **decrease possibility of collision**. Same goes to **Approach Macro Setting**.


❑ Cutting tool will be **approaching and leaving the workpiece in 90 degree** – **3 Axis** motion before make any **tilting motion** towards the machining profile.



Macro Setting –
Tool Axis


Multi-Axis Profile Contouring

- Once ALL settings from **TAB 1 – TAB 5** are **done**, **machining tool paths** is now can be calculated by hitting the icon **Tool Paths Reply**.
- This icon located at the bottom right of every TAB and appears the same on every machining operation offered.





Tool Paths Reply


Multi-Axis Profile Contouring



- ❑ **Specification TREE** – Multi-Axis Profile Contouring – 1st Side




Multi-Axis Profile Contouring




- From **Machining Tool Paths** calculation, it is **obviously** seen that the **cutting tool** is **approaching** the **material** in a **straight 90 degree motion** (from plane “a” – “b”)
- This is **due to the Approach Macro Setting** set which shows the function of **Tool Axis** motion.
- The **cutting tool** is **ONLY** allowed to tilt on certain height of the plane set.

Multi-Axis Profile Contouring



- The cutting tool is started to tilt towards the machining surface illustrated by “A”
- Meanwhile, “B” exhibits the cutting tool **begins machining process** on the respected surface perpendicularly.
- Ultimately, **Macro Setting** is very useful in **directing the cutting tool motions** according to the **users specification** which on the same time **improving the flexibility** in preparing **CAM Program**.

Multi-Axis Profile Contouring



➤ There are THREE (3) options given by CATIA in viewing the full machining simulation. The description are as follows


- 1 = Play video from last saved result
- 2 = Full Video
- 3 = Mixed Photo / Video

➤ Select 2nd icon to Play video from beginning.




➤ Once satisfied with full machining simulation then just click OK to return back to previous window


Multi-Axis Profile Contouring




End Simulation of Roughing Operation +
Finishing Profile Contouring Operation +
Multi-Axis Pocketing Operation



Multi-Axis Profile
Contouring– in progress




Front
View




Multi-Axis Profile Contouring -
Completed


Multi-Axis Profile Contouring




- ☐ **Specification TREE** – Profile Contou
– 1st Side
- ☐ Once complete, COPY & PASTE
same operation for the 2nd Hole.
- ☐ ONLY change TAB 2- Geometry –
Bottom, Guide Element & Top Surface



**Tool Paths Calculation
on another Side**




Multi-Axis Profile Contouring



End Simulation of
Roughing Operation +
Finishing Profile Contouring Operation +
Multi-Axis Pocketing Operation + Multi-Axis
Profile Contouring


Multi-Axis Profile Contouring



- By using **Multi-Axis Profile Contouring** **two (2)** slanted areas have been successfully machined.
- Now, **only one (1)** area left to be machined possibly using the same **machining operation (Multi -Axis Profile Contouring)**.
- The **following steps** shall **guide** on **how to perform Multi-Axis Profile Contouring Operation** on that particular area.

Multi-Axis Profile Contouring



2




- In this situation, the **Slanted Surface** is defined as **Bottom**, **Lower Line** is defined as **Guiding Element**, **Right Line** as **Limit 1** and **Left Line** as **Limit 2**.
- Remember, the moment **Bottom** is defined, the **Tool Axis** will be automatically calculated perpendicular to the surface selected.

Multi-Axis Profile Contouring



1




3




Multi-Axis Profile Contouring



Multi-Axis Profile Contouring




- Tool Paths calculation for slanted front surface
 - Multi-Axis Profile Contouring
 - **ISOMETRIC VIEW**




- Tool Paths calculation for slanted front surface
 - Multi-Axis Profile Contouring
 - **SIDE VIEW**
 - **Cutting Tool Position – 90 Degree**


Multi-Axis Profile Contouring



- Cutting Tool approaching in 90 degree on certain defined plane




- Cutting Tool started to tilt on certain degree perpendicularly to the selected surface




- Cutting Tool begin machining process in tilting position as per defined surface


Multi-Axis Profile Contouring




From End Simulation Result



Multi-Axis Profile Contouring
front slanted surface in progress




Side
View




Multi-Axis Profile Contouring -
Completed

Multi-Axis Profile Contouring



End Simulation of
Roughing Operation +
Finishing Profile Contouring Operation +
Multi-Axis Pocketing Operation + Multi-Axis Profile Contouring

Multi-Axis Profile Contouring




Exercise 1

Please prepare the CAM Programming following the instructions below:

- *Perform Multi-Axis Profile Contouring on the shown location.*
- *Please ensure the best practice of Macro Setting is used.*

Multi-Axis Profile Contouring



Exercise 2

Please prepare the CAM Programming following the instructions below:

- *Perform Multi-Axis Profile Contouring.*
- *Please ensure the best practice of Macro Setting is used.*

Multi-Axis Profile Contouring

ALL THE BEST

THANK YOU