

ADVANCED MACHINING

BETP 3584

INTRODUCTION TO ADVANCED MACHINING

5-AXIS CNC MACHINING CONCEPT

Syahrul Azwan bin Sundi @ Suandi
syahrul.azwan@utem.edu.my

Learning Outcomes

At the end of this course, students should be able to:

- ✓ **Explain** the basic operation principles and control systems of CNC machine.
- ✓ **Construct** Five-Axis CNC Programming for Milling operations.
- ✓ **Analyze** problem related with CNC Program using linear moves, circular moves and canned cycles.
- ✓ **Use** Five-Axis CNC Milling Machine.
- ✓ **Demonstrate** positive team working attributes by contributing actively in group projects.



Practical Application

The practical application consists of Five-Axis CNC Machining applications such as:

1. Facing and Roughing
2. Multiple Hole Drilling Operations – Machining Pattern.
3. Five-Axis Pocketing Operation.
4. Five-Axis Profile Contouring Operation.
5. Multi-Axis Flank Contouring Operation.
6. Multi-Axis Sweeping Operation.


1

2


3

Introduction

- ✓ 3-axis machining consists of **X**, **Y**, and **Z** directions
- ✓ There are **TWO** additional axes in 5-axis machining which rotates in every basic 3-axis axes
 - ✓ Along axis X is A
 - ✓ Along axis Y is B
 - ✓ Along axis Z is C




Advanced Machining Lab




5-AXIS CNC MILLING
MACHINE
HEIDENHEIN 640i
CONTROLLER
18,000 RPM

Advanced Machining Lab



5-AXIS
HIGH SPEED CNC MILLING
MACHINE
SIEMENS 840D CONTROLLER
24,000 RPM

Advanced Machining Lab



TURN MILL MULTI-AXIS CNC
MACHINE
CELOS
9-Axis (Main Spindle / Sub-Spindle
/ Lower Turret

Simultaneous Vs Positional

- **Positional / Indexing**
 - Motion of Discrete Operations
 - Improve cycle time due to single setup
- **Continuous / Simultaneous**
 - Movement of all related axes at one time along respected profile
 - The best for profiling parts and sculpture surfaces



Advantages

- **Creation of complex contours and parts**
 - Simultaneous motions and feed along all 5-axes
 - Flexibility of machined parts without casting process
 - Improved lead times
 - Higher accuracy attainable
- **Allows machining of ALL 5-Axes of parts**
 - Almost every angle of surfaces can be machined
 - Reduces time and cost of producing fixtures
 - Reduces inaccuracy in alignment due to multiple setups


Advantages

- **Shorter cutters can be used due to the flexibility of tilting angles**
 - Lower cutter loads, higher cutting speeds, longer tool life
 - Decreased vibration, better surface finish


Dis-Advantages

- Huge Initial investment
- Higher cost of tooling
- More complex
- Increased volume of code
- Highly skilled programmer or more sophisticated software required to generate tool paths
- Increased cost on training skilled workers


Generating Part Design for Computer Aided Manufacturing (CAM)



Given Part/Model




Stock Preparation



Specification TREE – Insert NEW Body – Renamed – Sketch – Pad


Generating Part Design for Computer Aided Manufacturing (CAM)



Plane System

PLANE SYSTEM

- Consist of THREE (3) Planes
- A POINT created as Start Reference Point
- HOME Plane (**100mm** from TOP stock surface)
- RAPID Plane (**30mm** from TOP stock surface)
- APPROACH Plane (**15mm** from TOP stock surface)
- Workpiece Coordinate System for Assembly



Specification Tree of Plane System

Generating Part Design for Computer Aided Manufacturing (CAM)




Entering **Assembly Design Workbench**




1. Identify the base using **FIX COMPONENT**

2. Match Model WPC Plane System WP Use **COINCIDENCE CONSTRAINTS**




Final Assembled Part







Generating Part Design for Computer Aided Manufacturing (CAM)



Overall Product
Specification TREE



Details of **CONSTRAINTS**
from Specification TREE


Entering Advanced Machining Workbench



Entering **Advanced Machining Workbench**

There are **FIVE (5) COMPULSORY** settings need to be made in **PART OPERATION**


1. **Type Of MACHINE**
2. **Workpiece Coordinate System (WPC)**
3. **Designated Part to be Machined file**
4. **Define Part to be Machined model**
5. **Define STOCK model**



Entering Advanced Machining Workbench




1. Type Of MACHINE



3-Axis Machine

3-Axis with Rotary Table Machine




5-Axis Machine



Entering Advanced Machining Workbench




2. Workpiece Coordinate System (WPC)




Entering Advanced Machining Workbench



3. Designated Part to be Machined file



Select the section as highlighted above





Find and choose the desired CAD Model. The **BEST** format to export is **.CATProduct**. But **.CATPart** can be used as well

Entering Advanced Machining Workbench



4. Define Part to be Machined model





Select Model


Entering Advanced Machining Workbench



4. Define STOCK model




Define Stock




Entering Advanced Machining Workbench




Creating **CUTTING TOOLS** in
Resources List



Please **ANALYSE** the CAD Model and list
down your cutting tools before creating and
inserting the tools




Entering Advanced Machining Workbench



RULER – can be used to measure distance between two profile, length, angle ect.



Caliper - can be used to measure diameter / radius of hole. This function also normally used to analyze the general shape of any given profiles



Entering Advanced Machining Workbench



Once any given part has been **ANALYSED** then a list of **REQUIRED CUTTING TOOLS** need to be created before begin the machining process programming.


There are various cutting tools options are given by CATIA V5 as shown above namely (*from left*):

- | | | |
|-------------------------|--------------------------|---------------------|
| 1. Drill | 9. Boring & Chamfering | 17. Barrel Mill |
| 2. Tap | 10. Two Sides Chamfering | 18. Ball Stylus |
| 3. Thread Mill | 11. Boring Bar | 19. Cylinder Stylus |
| 4. Countersink | 12. Counterbore | |
| 5. Reamer | 13. End Mill | |
| 6. Center Drill | 14. Face Mill | |
| 7. Spot Drill | 15. Conical Mill | |
| 8. Multi-Diameter Drill | 16. T-Slotter | |

Entering Advanced Machining Workbench




List of created **CUTTING TOOLS** in
Resources List



Entering Advanced Machining Workbench




Exercise 1 : Safety Key



Entering Advanced Machining Workbench




Exercise 2 : Pen & Sticky Notes Holder



Entering Advanced Machining Workbench




Exercise 3 : Balsa Wood Mold



Entering Advanced Machining Workbench



Exercise 4 : Bearing Housing



Entering Advanced Machining Workbench

ALL THE BEST

THANK YOU